
Continuous
powergui
Current Measurement
Multimeter
Mag
Fourier
Phase
Fourier1
Display2
Gain1
-K-
Math
Function
u^2
Gain
30/pi
26.7
Constant
Fourier
Display1
Display
AC Voltage Source
AC Voltage Source1
AC Voltage Source2
Three-Phase
Series RLC Branch
Three-Phase Breaker
Tm
Asynchronous Machine
SI Units
<Stator current is_a (A)>
<Rotor speed (wm)>
<Electromagnetic torque Te (N*m)>
Scope
Voltage Measurement
Fourier2
Display3
Voltage Measurement2
Display5
Voltage Measurement1
Fourier3
Display4
Divide
Scope1
Mean
Mean Value
Display6
26.7
Constant1
Asynchronous Machine
SI Units1
Scope2