

FORMULARIO 2

MÁQUINA ASÍNCRONA

$$T_i = \frac{P_g}{\Omega_s} = \frac{3 \cdot V_{th}^2 \cdot \frac{R_R'}{S}}{\left[R_{th} + \frac{R_R'}{S} \right]^2 + [X_{th} + X_R']^2} \cdot \frac{1}{\Omega_s}$$

$$T_{ARR} = \frac{3}{\Omega_s} \cdot \frac{R_R' \cdot V_{th}^2}{[R_{th} + R_R']^2 + [X_{th} + X_R']^2}$$

$$I_{ARR} = \frac{V_{th}}{[R_{th} + R_R']^2 + [X_{th} + X_R']^2}$$

$$\underline{V}_{th} = \frac{\frac{U_{2n}}{\sqrt{3}} \cdot jX_\mu}{R_S + j[X_S + X_\mu]} \quad \underline{Z}_{th} = \frac{[R_S + jX_S] \cdot jX_\mu}{R_S + j[X_S + X_\mu]}$$

$$T_{max} = \frac{3V_{th}^2}{2\Omega_s \cdot \left[R_{th} + \sqrt{R_{th}^2 + [X_{th} + X_R']^2} \right]}$$

$$S_{TMAX} = \frac{R_R'}{\sqrt{R_{th}^2 + [X_{th} + X_R']^2}}$$